



NHIW CERTIFICATION

Please read instructions prior to completing this form.

Generator Name: US EPA Region 6/ Wilcox Oil Company Site

Mailing Address: 1201 Elm Street City Dallas State TX Zip 75270

Point of Generation Address: 35146 E0810 City Bristow State OK Zip 74010

Generator Contact: Katrina Coltrain Title Remedial Project Manager Telephone 214-665-8143

DETAILED WASTE DESCRIPTION

Waste Name: NON DOT/NON RCRA contaminated soil

If waste was generated out-of-state, is it classified as hazardous in the state of origin? ☐ Yes ☐ No ☒ NA- Okla. waste

Approximate amount of waste to be disposed:

Disposal frequency:

Physical characteristics:

70,000 ☒ Tons ☐ Pounds ☒ One-time ☐ Weekly ☒ Solid ☐ Liquid
☐ Cubic yards ☐ Drum ☐ Monthly ☐ Annually ☐ Sludge ☐ Combination
☐ Other

Method used to determine waste is non-hazardous: ☒ Analysis ☐ Generator knowledge ☐ Both

Process generating waste (be specific and use additional sheets if necessary):

US EPA Region 6 CERCLA removal located at a former oil refining and tank farm facility in Bristow, OK.

Data was taken during the remedial design work for this project.

The site is closed and there has been no changes to the site since this data was taken.

Material includes 85-90% Soil, 1-5% Vegetation, 1-5 % PPE/Poly Sheeting, 1-5% Geofabric, 1-5%

DESIGNATED RECEIVING LANDFILL

Name: American Environmental Landfill Permit #:

GENERATOR CERTIFICATION

I understand this form must be signed by the original waste generator or other persons authorized by 27A O.S. §2-10-501(H).

To the best of my knowledge, I certify:

- ♦ The information contained herein is accurate, complete, and representative of the waste to be disposed;
- ♦ The waste identified above is not a characteristically hazardous waste as identified by 40 CFR 261, Subpart C, is not a listed hazardous waste as identified by 40 CFR 261, Subpart D or contaminated with a listed hazardous waste, and is not otherwise identified as a hazardous waste by the Department of Environmental Quality; and
- ♦ This waste will be managed in accordance with all applicable statutes and rules of the Department of Environmental Quality.

US EPA

Generator Signature

Katrina Higgins-Coltrain on behalf of US EPA Region 6

Remedial Project Manager

7/8/22

Printed name

Adopted June 2003

KATRINA HIGGINS-COLTRAIN

Digitally signed by KATRINA HIGGINS-COLTRAIN
Date: 2022.07.14 07:38:44 -05'00'

Title

Date

DEQ Form # 515-860

INSTRUCTIONS FOR COMPLETING THE NHIW CERTIFICATION

Enter the name of the generating facility, generator mailing address, address where the waste was generated, contact name and title of person at the generating facility who is knowledgeable about the waste, and phone number.

DETAILED WASTE DESCRIPTION

1. Identify the name of the waste.
2. Identify the approximate amount of waste to be disposed under the plan, its frequency of disposal, and its physical characteristics.
3. Identify if the waste was determined to be non-hazardous by either knowledge of process, testing, or both. If requested by DEQ, the generator must be able to provide information about the waste, such as a list of chemical constituents entering into the waste and a list of chemical constituents likely to be in the waste, laboratory analyses, MSDS sheets, and other information used by the generator to determine the waste is non-hazardous.
4. Identify the process generating the waste. Please note that the waste generating description must be specific and sufficient to demonstrate the waste is non-hazardous.

DESIGNATED RECEIVING LANDFILL

Identify the name of the landfill to receive the waste and its DEQ permit number.

GENERATOR CERTIFICATION

Read the certification and sign and date the form. **Please note that the certification may only be dated and signed by one of the following:** 1) the original waste generator; 2) a person who identifies and is under contract with a generator and whose activities under the contract cause the waste to be generated; 3) a party to a remediation project under an order of the DEQ or under the auspices of the Oklahoma Energy Resources Board or other agencies of other states; or 4) a person responding to an environmental emergency.

The completed notification form should be submitted to the DEQ at the following address. Once submitted, the generator may dispose of the waste at the designated landfill.

Department of Environmental Quality
Solid Waste Compliance Unit
P. O. Box 1677
Oklahoma City, OK 73102
Phone (405) 702-5100
Fax (405) 702-5101